

LD-IC-TD2 Revision History

LD-IC-TD2 Revision											Revision Description	TB #	ECN #	Date
LD12/20-2/3S	IC1,2,3,4	TD2												
1025	1121	1191									Book & PDF Number			
A1.00	A1.00	A1.01									Introducing into production			
B1.00											Change in construction of loader arm. Now is welded before was bolted. Added cover over the LD12/20 control box	#110022pl	#5671	12/08/2011
	A2.00										Change in construction of belt tensioner.		#5672	05/03/2012