

Begin 2008 revision record

SLP Revision History

SLP Revision										Revision Description	TB #	ECN #	Date
TVS	HR500	HR1000 (MH)	SVS	TVSFT	HR115	HR110	TVS-SC						
1001 1004	1006		1008 1009	1003 1005	924 925	926 927	1017 1018			Book & PDF Number			
A1.00	A1.00		A1.00							Introducing into production			
A2.00										Change the place where the calibration sensor is mounted Added the sawdust scraper on the feed chain tensioning wheel	080022pl 080024pl	4256 4259	6/08/2008 14/08/2008
A2.01	A1.01		A1.01							Blade Speed Reduction	090010pl	4470	11/05/2009
A2.02	A1.02		A1.02							New Blade Guide Rollers	090012pl	4469	08/06/2009
				A1.00						New product			
A3.00	A2.00		A2.00	A2.00						CE Electrical Connections Change		4810	14/12/2009
A4.00			A3.00							Blade Tensioner Complete		4816	12/01/2010
	A3.00									New Blade Drive Wheel & Bushing	100001pl	4468	15/02/2010
A4.01			A3.01	A2.01						Lasers change	100013pl	5008	03/2010 (red beam) 26/04/210 green beam)
A5.00										A new TVS 02 without calibration sensor.	100017pl	4997	17/05/2010
A5.01										The new TBS01 Setworks Controller (Part No. 503467)	100022pl	5160	03/08/2010
	A3.01									Feed Track Pads	100023pl	5203	23/08/2010
		A2.00								New Nomenclature		5023 5140	22/09/2010 02/08/2010
					A1.00	A1.00				New products			09/2010
A6.00				A3.00						New TVS Control Box	100032pl	5256	01/12/2010
							A1.00			New product			
					A1.00	A1.00				LT10 & LT15 and HR110 & HR115 Saw Head Unification (Blade Guide Tube)	#110007pl	#5512	18/03/2011
A7.00			A4.00	A4.00			A2.00			Hydraulic Blade Tensioner with blade brake pressure switch	#110018pl	#5466 #5596	30/05/2011
					A2.00	A2.00				New Blade Guide Roller Brackets	#110019pl	#5715	13/06/2011
		A3.00								New Drive Belt Tensioner		#5410	27.06.2011
		A4.00								New HydraulicTank Assembly		#5918	01.01.2012
						A2.01				Changed Saw Head in HR110		#5921	06.12.2011